



## MATT BIRCHBY 502362 VOLVO PENTA 3940021485 - PORT IPS

Sample No: VPA059632

**Oil Type:** VOLVO API GL-5 SAE 75W90

SAMPLE INFORMA	ATION			
Sample Number		VPA059632	 	
Sample Date		20 Sep 2023	 	
Machine Hours		471	 	
Oil Hours		50	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	109	 	
CONTAMINATION				
Silicon	ppm	6	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>2</b>	 	
	1.1.			
WEAR METALS				
PQ		<b>20</b>	 	
Iron	ppm	<b>■34</b>	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b></b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>■</b> 4	 	
Magnesium	ppm	<b>2</b>	 	
Zinc	ppm	■0	 	
Phosphorus	ppm	■1322	 	
Barium	ppm	■0	 	
Boron	ppm	<b>318</b>	 	
20.011	PPIII			

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW

SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP794951

 Unique No:
 10660469

 Signed:
 Don Baldridge

 Report Date:
 26 Sep 2023

## **OIL ANALYSIS REPORT**



