



## NADINE URCIUOLI OUTER LIMITS 2300468 VOLVO PENTA OUTER LIMITS (S/N N/A) - PORT DIESEL ENGINE

Sample No: VPA049573

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

SAMPLE INFORMAT	TION			
Sample Number		VPA049573	 	
Sample Date			 	
Machine Hours		14 Sep 2023 11153		
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ATTENTION	 	
OIL CONDITION				
Visc @ 100°C	cSt	<u> </u>	 	
Base Number (BN)	mg KOH/g	<b>7.4</b>	 	
Oxidation (PA)	%	46	 	
CONTAMINATION				
Soot %	%	■ 0.1	 	
Nitration (PA)	%	60	 	
Sulfation (PA)	%	47	 	
Glycol	%	NEG	 	
Fuel	%	<b>△</b> 3.6	 	
Silicon	ppm	<b>■</b> 3	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>1</b>	 	
WEAR METALS				
	10.10.100			
Iron	ppm	<b>3</b>		
Copper	ppm	<b>13</b>	 	
Lead 	ppm	<b>■</b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>0</b>	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>6</b>	 	
Nickel	ppm	■0	 	
Titanium	ppm	<b>□</b> <1	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■</b> <1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<b>1319</b>	 	
Magnesium	ppm	<b>732</b>	 	
Zinc	ppm	<b>■</b> 803	 	
Phosphorus	ppm	<b>■</b> 685	 	
Barium		<b>0</b> 0	 	
Boron	ppm	<b>■</b> 69		
DOIOII	ppm	<b>■</b> 03	 	

## **Helmuts Marine Service**

619 Canal Street SAN RAFAEL, CA US 94901-3545 Contact: NADINE URCIUOLI SERVICE@HELMUTSMARINE.COM

T: x: F: x:

## Diagnosis

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. Light fuel dilution occurring. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VP152741Unique No:10661545Signed:Jonathan HesterReport Date:27 Sep 2023

## **OIL ANALYSIS REPORT**



