

OIL ANALYSIS REPORT

**VOLVO
PENTA**

AMERICAN MARINE M772881 2006032404 - PORT COOLANT

Sample No: VPA051750

Oil Type: VOLVO COOLANT (GREEN)

SAMPLE INFORMATION

Sample Number	VPA051750	---	---	---
Sample Date	02 Oct 2023	---	---	---
Machine Hours	523	---	---	---
Sample Status	ABNORMAL	---	---	---

COOLANT CONDITION

pH	Scale 0-14	■ 8.48	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 1240	---	---	---
Percentage Glycol	%	■ 53.7	---	---	---
Freezing Point	°C	■ -43	---	---	---

CONTAMINATION

Coolant Appearance	▲ sediment	---	---	---
Coolant Color	Yllow	---	---	---

INTERSTATE POWER SYSTEMS

2901 E 78TH ST
MINNEAPOLIS, MN
US 55425

Contact: BRADY GARBRECHT
brady.garbrecht@istate.com

T:
F:

Diagnosis

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. We advise that you replenish the supplemental coolant additives (SCAs) and add per manufacturer's recommendations. Sediment present. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VP1103105
Unique No: 10683846
Signed: Jonathan Hester
Report Date: 12 Oct 2023

OIL ANALYSIS REPORT



GRAPHS

