

OIL ANALYSIS REPORT

**VOLVO
PENTA**

WAVE DANCER 11087 NORTHERN LIGHTS 8432-52204 - GENSET

Sample No: VPA059664

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMATION

Sample Number	VPA059664	---	---	---
Sample Date	11 Oct 2023	---	---	---
Machine Hours	1938	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 100°C	cSt	█ 14.2	---	---	---
Base Number (BN)	mg KOH/g	█ 8.2	---	---	---
Oxidation (PA)	%	65	---	---	---

CONTAMINATION

Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	59	---	---	---
Sulfation (PA)	%	57	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	<1.0	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 8	---	---	---

WEAR METALS

Iron	ppm	█ 10	---	---	---
Copper	ppm	█ 2	---	---	---
Lead	ppm	█ 1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ 6	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	█ 1961	---	---	---
Magnesium	ppm	70	---	---	---
Zinc	ppm	█ 1092	---	---	---
Phosphorus	ppm	█ 926	---	---	---
Barium	ppm	█ 2	---	---	---
Boron	ppm	█ 148	---	---	---

Hinckley Yacht Services

1 Little Harbor Lndg
PORTSMOUTH, RI
US 02871-6115
Contact: Christopher Manghan
cmanghan@hinckleyyachts.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VP155302
Unique No: 10688769
Signed: Sean Felton
Report Date: 13 Oct 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

