



GREG BOHMANN BH UNIVERSAL 500991 - DIESEL ENGINE

Sample No: VPA048598
Oil Type: NOT GIVEN

Camamia Nii		VDA040500	·	
Sample Number		VPA048598		
Sample Date		25 Sep 2023		
Machine Hours		0		
Oil Hours		0		
Oil Changed		Changed NORMAL		
Sample Status		NORWIAL		
OIL CONDITION				
Visc @ 100°C	cSt	■11.8		
Base Number (BN)	mg KOH/g	10.0		
Oxidation (PA)	%	40		
CONTAMINATION				
	0/			
Soot % Nitration (PA)	%	□ 1 57		
Sulfation (PA)	%	53		
Glycol	%	NEG		
Fuel	%	■ 1.9		
Silicon		1.9		
Sodium	ppm	4		
Potassium	ppm	2		
WEAR METALS	ppiii			
		=		
Iron	ppm	27		
Copper	ppm	3		
Lead 	ppm	2		
Tin Aluminum	ppm	2		
	ppm	□ 5		
Chromium	ppm	2		
Molybdenum	ppm	46		
Nickel Titanium	ppm			
	ppm	<1		
Silver	ppm	0		
Manganese Vanadium	ppm	<1 0		
	ppm	0		
ADDITIVES				
Calcium	ppm	■3658		
Magnesium	ppm	■29		
Zinc	ppm	1196		
Phosphorus	ppm	■988		
Barium	ppm	■ 0		
Boron	ppm	■382		

CHICAGO YACHT WORKS

2550 S ASHLAND AVE CHICAGO, IL US 60608 Contact: JONATHAN PAIGE jonathan@chicagoyachtworks.com T: (312)666-6670 F:

Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP1080862Unique No:10695327Signed:Don BaldridgeReport Date:16 Oct 2023

OIL ANALYSIS REPORT



