## **OIL ANALYSIS REPORT**

# **VOLVO PENTA**

### QUICK SPIN QUICK SPIN VOLVO PENTA 3940015641 - STARBOARD IPS

Sample No: VPA055215

Oil Type: NOT GIVEN

### SAMPLE INFORMATION

Sample Number		VPA055215	 		
Sample Date		17 Oct 2023		 	MARINE DIESEL SE 1711 WHITTIER AVE COSTA MESA, CA
Machine Hours		435		 	
Oil Hours		14		 	
Oil Changed		N/A		 	US 92627
Sample Status		NORMAL		 	Contact: BEN ALM marinedieselservio
OIL CONDITION					T: (949)612-8180
Visc @ 40°C	cSt	<b>109.0</b>		 	F: x:
CONTAMINATION	N				Diagnosis
Silicon	ppm	9		 	No corrective act at this time. Resa
Sodium	ppm	6		 	service interval to
Potassium	ppm	2		 	component wear
WEAR METALS					There is no indica contamination in
PQ		<b>1</b> 4		 	condition of the c the time in service
Iron	ppm	<b>1</b> 4		 	
Copper	ppm	5		 	
Lead	ppm	<1		 	
Tin	ppm	0		 	
Aluminum	ppm	0		 	
Chromium	ppm	0		 	
Molybdenum	ppm	0		 	
Nickel	ppm	0		 	
Titanium	ppm	0		 	
Silver	ppm	<1		 	
Manganese	ppm	<1		 	
Vanadium	ppm	0		 	
ADDITIVES					
Calcium	ppm	3		 	_
Magnesium	ppm	2		 	
Zinc	ppm	4		 	
Phosphorus	ppm	973		 	
Barium	ppm	0		 	
Boron	ppm	187		 	

#### **RVICES INC**

SUITE B ΆN @outlook.com

is recommended le at the next onitor.All es are normal. n of any oil. The s acceptable for


Depot:	VP288530		
Unique No:	10699983		
Signed:	Doug Bogart		
Report Date:	18 Oct 2023		

Contact/Location: BEN ALMAZAN - VP288530

## **OIL ANALYSIS REPORT**



### GRAPHS



Report Id: VP288530 [WUSCAR] 05982688 (Generated: 10/18/2023 16:37:11) Rev: 1

Contact/Location: BEN ALMAZAN - VP288530