



## OUICK SPIN OUICK SPIN VOLVO PENTA 39400 15640 - PORT IPS

Sample No: VPA050984
Oil Type: NOT GIVEN

SAMPLE INFORMA	TION			
SAMPLE INFORMA	ATION			
Sample Number		VPA050984	 	
Sample Date		17 Oct 2023	 	
Machine Hours		434	 	
Oil Hours		14	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>107.2</b>	 	
CONTAMINATION				
		•		
Silicon	ppm	9	 	
Sodium	ppm	<b>5</b>	 	
Potassium	ppm	<b>0</b>	 	
WEAR METALS				
PQ		<b>17</b>	 	
Iron	ppm	<b>■</b> 9	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	0	 	
Magnesium	ppm	<1	 	
Zinc	ppm	0	 	
Phosphorus	ppm	1376	 	
Barium	ppm	0	 	
Boron	ppm	323	 	
DOTOTI	PPIII	323		

## MARINE DIESEL SERVICES INC

1711 WHITTIER AVE, SUITE B
COSTA MESA, CA
US 92627
Contact: BEN ALMAZAN
marinedieselservices@outlook.com
T: (949)612-8180

F: x:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP288530Unique No:10699984Signed:Doug BogartReport Date:18 Oct 2023





