



## FINN H15314 VOLVO PENTA FINN - VPAO36437 (S/N NOT GIVEN) - STARBOARD DIESEL ENGINE

Sample No: VPA036437

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
		VD4026427		
Sample Number		VPA036437	 	
Sample Date		17 Oct 2023	 	
Machine Hours		209	 	
Oil Hours		70	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>14.8</b>	 	
Base Number (BN)	mg KOH/g	■8.8	 	
Oxidation (PA)	%	65	 	
CONTAMINATION				
Soot %	%	<b>■</b> 0.7	 	
Nitration (PA)	%	58	 	
Sulfation (PA)	%	59	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>■13</b>	 	
Sodium	ppm	<b>■2</b>	 	
Potassium	ppm		 	
	pp		 	
WEAR METALS				
Iron	ppm	<b>14</b>	 	
Copper	ppm	<b>■</b> 23	 	
Lead	ppm	<b>■</b> <1	 	
Tin	ppm	1	 	
Aluminum	ppm	2	 	
Chromium	ppm	_ <1	 	
Molybdenum	ppm	<b>1</b> 4	 	
Nickel	ppm	_ 1	 	
Titanium	ppm	<b>■</b> 0	 	
Silver	ppm	<b>■</b> <1	 	
Manganese	ppm	<b>■</b> <1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<b>2264</b>	 	
Magnesium	ppm	89	 	
Zinc	ppm	<b>1312</b>	 	
Phosphorus	ppm	 <b>1044</b>	 	
Barium	ppm	<b>■</b> 0	 	
Boron	ppm	<b>170</b>	 	

## Walstrom Marine - 767948

501 Bay Street
HARBOR SPRINGS, MI
US 49740
Contact: MARK LEWIS
mlewis@walstrom.com
T:
F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP154879Unique No:10708785Signed:Don BaldridgeReport Date:25 Oct 2023

Contact/Location: MARK LEWIS - VP154879

## **OIL ANALYSIS REPORT**



