



## BLACKSTONE VOLVO PENTA A 1052431 STERNDRIVE - STARBOARD GEARBOX

Sample No: VPA049869
Oil Type: NOT GIVEN

SAMPLE INFORM	ATION			
Sample Number		VPA049869	 	
Sample Date		22 Oct 2023	 	
Machine Hours		175	 	
Oil Hours		60	 	
Oil Changed		Not Changd	 	
Sample Status		MARGINAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>103.7</b>	 	
CONTAMINATION				
Silicon	ppm	<b>■</b> 4	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>1</b>	 	
WEAR METALS				
		=22		
PQ	10.10.100	■22 ▲ 170	 	
Iron	ppm	■1	 	
Copper Lead	ppm	■ I ■ <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<u> </u>	 	
Chromium	ppm	<b>■</b> 2	 	
Molybdenum	ppm	1	 	
Nickel	ppm	7	 	
	ppm	_		
Titanium	ppm	<1	 	
Silver	ppm	0 6	 	
Manganese Vanadium	ppm	0	 	
	ppm	<u> </u>	 	
ADDITIVES				
Calcium	ppm	17	 	
Magnesium	ppm	21	 	
Zinc	ppm	51	 	
Phosphorus	ppm	1681	 	
Barium	ppm	0	 	
Boron	ppm	387	 	

## **Outstanding Marine**

PO Box 274 GALENA, MD US 21635 Contact: Ronda Bolinger rlwb@verizon.net T:

## Diagnosis

F:

No corrective action is recommended at this time. We recommend an early resample to monitor this condition. Gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP153685Unique No:10709738Signed:Doug BogartReport Date:23 Oct 2023

## OIL ANALYSIS REPORT



