## **OIL ANALYSIS REPORT**

### KELLY BUSEY 7717116 VOLVO PENTA 50630341403 - INBOARD - STARBOARD GEARBOX

Sample No: VPA036240

Oil Type: DEXRON III

#### SAMPLE INFORMATION Sample Number VPA036240 02 Oct 2023 Sample Date Machine Hours 1450 0 **Oil Hours** N/A Oil Changed NORMAL Sample Status **OIL CONDITION** F: Visc @ 40°C cSt 26.2 CONTAMINATION Silicon ppm ■ <1</p> Sodium ppm 0 Potassium 1 ppm WEAR METALS PO 12 Iron 3 ppm Copper ppm 5 Lead ppm 1 Tin ppm **||** <1 2 Aluminum ppm Chromium ppm **||** <1 Molybdenum ■<1 ppm Nickel 0 🔲 ppm Titanium ppm <1 Silver 0 ppm Manganese 0 ppm Vanadium 0 ppm ADDITIVES Calcium 8 ppm Magnesium 2 ppm Zinc ppm 3 Phosphorus ppm 178 11 Barium ppm 66 Boron ppm

Pacific Power Group - VP981534 7215 S 228th St Kent, WA US 98032 Contact: MARINE SERVICES MarineService@pacificpowergroup.com T: (253)520-5151

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP99031103

 Unique No:
 10710206

 Signed:
 Sean Felton

 Report Date:
 25 Oct 2023


Contact/Location: MARINE SERVICES - VP99031103



# **OIL ANALYSIS REPORT**



#### GRAPHS



Contact/Location: MARINE SERVICES - VP99031103