OIL ANALYSIS REPORT

CARLA STRATFORD DILLON WESTERBEKE 2125367 - STARBOARD GENSET

Sample No: VPA059056

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

SAMPLE INFORMATION VPA059056 Sample Number Endor Marine LLC - Coastal Marine - 152124 19 Oct 2023 Sample Date Machine Hours 33 33 **Oil Hours** Oil Changed Changed ATTENTION Sample Status **OIL CONDITION** Visc @ 100°C cSt **11.4** Base Number (BN) mg KOH/g 6.9 Oxidation (PA) % 27 CONTAMINATION Soot % % 0.1 % Nitration (PA) 34 Sulfation (PA) % 38 % Glycol NEG Fuel % 1.1 Silicon ppm 36 Sodium 6 ppm Potassium 0 🔲 ppm WEAR METALS ppm 10 Iron Copper 8 ppm Lead ppm 0 Tin ■ <1 ppm Aluminum 4 ppm Chromium **||** < 1 ppm Molybdenum 31 ppm Nickel 0 ppm Titanium <1 ppm Silver ppm 0 Manganese 2 ppm Vanadium 0 ppm ADDITIVES Calcium 1656 ppm Magnesium 121 ppm Zinc ppm 865 Phosphorus ppm 583 Barium ppm 4

Contact/Location: WILLOW YANARELLA - VP794951

Depot: Unique No:

Signed:

Report Date:

VP794951

10711556

Sean Felton

27 Oct 2023

ppm

Boron

146

4300 11th Ave. NW SEATTLE, WA US 98107 Contact: WILLOW YANARELLA service@coastalmarineengine.com T: (206)784-3703 F: (206)784-8823

Diagnosis


Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.Metal levels are typical for a new component breaking in. Fuel content negligible. No other contaminants were detected in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.



OIL ANALYSIS REPORT



GRAPHS



Report Id: VP794951 [WUSCAR] 05988894 (Generated: 10/31/2023 13:09:45) Rev: 2

Contact/Location: WILLOW YANARELLA - VP794951