



## CARRUTHERS CODY CUMMINS K060990074 - GENSET

Sample No: VPA036436

**Oil Type:** DIESEL ENGINE OIL SAE 40

SAMPLE INFORMAT	TION			
Sample Number		VPA036436	 	
Sample Date		20 Oct 2023	 	
Machine Hours		700	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.9</b>	 	
Base Number (BN)	mg KOH/g	■9.3	 	
Oxidation (PA)	%	65	 	
` '				
CONTAMINATION				
Soot %	%	<b>■</b> 0.1	 	
Nitration (PA)	%	57	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon		□ 5	 	
	ppm			
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	■0	 	
WEAR METALS				
Iron	ppm	<b>2</b>	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	□0	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>■ &lt;1</b>	 	
Chromium	ppm	0	 	
Molybdenum		<b>44</b>	 	
Nickel	ppm	<b>0</b>	 	
	ppm	_		
Titanium	ppm	<b>0</b>	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>■</b> <1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>1429</b>	 	
Magnesium	ppm	<b>637</b>	 	
Zinc	ppm	<b>1225</b>	 	
Phosphorus	ppm	■868	 	
Barium	ppm	■0	 	
Boron	ppm	<b>1</b> 76	 	
DOTOIT	Phili			

## Walstrom Marine - 767948

501 Bay Street HARBOR SPRINGS, MI US 49740 Contact: MARK LEWIS mlewis@walstrom.com T:

## Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP154879

 Unique No:
 10711557

 Signed:
 Sean Felton

 Report Date:
 27 Oct 2023

## **OIL ANALYSIS REPORT**



