

OIL ANALYSIS REPORT

VOLVO PENTA

LEO POCIUS CUMMINS C120318745 - GENSET

Sample No: VPA059805

Oil Type: VOLVO ROTELLA 15W40

SAMPLE INFORMATION

Sample Number	VPA059805	---	---	---
Sample Date	24 Oct 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

BAY MARINE

3 E MADISON ST

WAUKEGAN, IL

US 60085

Contact: BRENDAN COWHEY

brendan@baymarine.net

T: (847)336-2628

F:

OIL CONDITION

Visc @ 100°C	cSt	█ 14.1	---	---	---
Base Number (BN)	mg KOH/g	8.3	---	---	---
Oxidation (PA)	%	67	---	---	---

CONTAMINATION

Soot %	%	█ 0.1	---	---	---
Nitration (PA)	%	56	---	---	---
Sulfation (PA)	%	56	---	---	---
Glycol	%	NEG	---	---	---
Fuel	%	<1.0	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 4	---	---	---

WEAR METALS

Iron	ppm	█ <1	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	12	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	<1	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	1909	---	---	---
Magnesium	ppm	232	---	---	---
Zinc	ppm	1213	---	---	---
Phosphorus	ppm	877	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	137	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP1174336

Unique No: 10711564

Signed: Sean Felton

Report Date: 27 Oct 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

