

OIL ANALYSIS REPORT

VOLVO PENTA

DIAMOND VOLVO PENTA 3940016204 - PORT IPS

Sample No: VPA056736

Oil Type: NOT GIVEN

SAMPLE INFORMATION

Sample Number	VPA056736	VPA042938	---	---
Sample Date	24 Oct 2023	02 Sep 2022	---	---
Machine Hours	0	0	---	---
Oil Hours	0	0	---	---
Oil Changed	N/A	N/A	---	---
Sample Status	NORMAL	NORMAL	---	---

MAKO MARINE

117 HUDSON AVE

FREEPORT, NY

US 11520

Contact: PAUL FLOOD

makomarine@optonline.net

T: (516)378-7331

F: x:

OIL CONDITION

Visc @ 40°C	cSt	█ 105	█ 110	---	---
-------------	-----	-------	-------	-----	-----

CONTAMINATION

Silicon	ppm	█ 4	█ 10	---	---
Sodium	ppm	█ 2	█ 8	---	---
Potassium	ppm	█ 0	█ 0	---	---

WEAR METALS

PQ		█ 18	█ 14	---	---
Iron	ppm	█ 17	█ 63	---	---
Copper	ppm	█ 4	█ 8	---	---
Lead	ppm	█ 0	█ 0	---	---
Tin	ppm	█ 0	█ 0	---	---
Aluminum	ppm	█ 0	█ 1	---	---
Chromium	ppm	█ 0	█ <1	---	---
Molybdenum	ppm	█ <1	█ <1	---	---
Nickel	ppm	█ <1	█ 0	---	---
Titanium	ppm	█ <1	█ 0	---	---
Silver	ppm	█ 0	█ 0	---	---
Manganese	ppm	█ <1	█ 1	---	---
Vanadium	ppm	█ 0	█ 0	---	---

ADDITIVES

Calcium	ppm	█ 25	█ 17	---	---
Magnesium	ppm	█ 0	█ 3	---	---
Zinc	ppm	█ 0	█ 27	---	---
Phosphorus	ppm	█ 1042	█ 1347	---	---
Barium	ppm	█ 0	█ 2	---	---
Boron	ppm	█ 269	█ 376	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP1134331

Unique No: 10714475

Signed: Sean Felton

Report Date: 31 Oct 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

