



BRIAN TEDESCHI 533225 VOLVO PENTA 3940024032 - CENTER IPS

Sample No: VPA056996

Oil Type: GEAR OIL SAE 75W90

CAMPLE INCORM	ATION			
SAMPLE INFORM	ATIUN			
Sample Number		VPA056996	VPA025416	
Sample Date		31 Oct 2023	21 Oct 2021	
Machine Hours		2054	0	
Oil Hours		0	150	
Oil Changed		N/A	Not Changd	
Sample Status		SEVERE	ATTENTION	
OIL CONDITION				
Visc @ 40°C	cSt	■ 97.5	□109	
CONTAMINATION				
Water	%	△ 0.243		
Silicon	ppm	18	14	
Sodium	ppm	18	■8	
Potassium	ppm	■<1	- <1	
WEAR METALS				
PQ		■ 35	□ 231	
Iron	ppm	434	△ 216	
Copper	ppm	27	1 1	
Lead	ppm	0	<1	
Tin	ppm	0	0	
Aluminum	ppm	6	5	
Chromium	ppm	■3	2	
Molybdenum	ppm	□ 0	- <1	
Nickel	ppm	4	2	
Titanium	ppm	0	<1	
Silver	ppm	0	<1	
Manganese	ppm	4	2	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	7	2	
Magnesium	ppm	<u> </u>	2	
Zinc	ppm	<u> </u>	0	
Phosphorus	ppm	1278	1403	
Barium	ppm	■0	0	
Boron	ppm	■281	□331	
		_	_	

Jas Marine Service Inc 3131 SW 2Nd Ave. FORT LAUDERDALE, FL US 33315 Contact: JASON TOLEDO jason@jasmarine.com T: (954)462-1112

Diagnosis

F:

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is a light concentration of water present in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:VP426065Unique No:10724774Signed:Sean FeltonReport Date:03 Nov 2023

OIL ANALYSIS REPORT



