

OIL ANALYSIS REPORT

VOLVO PENTA

ROGER CONDO 42881 VOLVO PENTA 3950005656 - STARBOARD IPS

Sample No: VPA055618

Oil Type: VOLVO PENTA GL-5 SAE 75W90

SAMPLE INFORMATION

| | | | | |
|---------------|--------------------|-------------|-----|-----|
| Sample Number | VPA055618 | VPA033921 | --- | --- |
| Sample Date | 01 Nov 2023 | 20 Mar 2023 | --- | --- |
| Machine Hours | 471 | 366 | --- | --- |
| Oil Hours | 0 | 0 | --- | --- |
| Oil Changed | Changed | Changed | --- | --- |
| Sample Status | NORMAL | NORMAL | --- | --- |

OIL CONDITION

| | | | | | |
|-------------|-----|------------|-------|-----|-----|
| Visc @ 40°C | cSt | 138 | █ 106 | --- | --- |
|-------------|-----|------------|-------|-----|-----|

CONTAMINATION

| | | | | | |
|-----------|-----|----------------|------|-----|-----|
| Silicon | ppm | <1 | █ 1 | --- | --- |
| Sodium | ppm | █ <1 | █ <1 | --- | --- |
| Potassium | ppm | █ 0 | █ 2 | --- | --- |

WEAR METALS

| | | | | | |
|------------|-----|-------------|------|-----|-----|
| PQ | | █ 12 | █ 19 | --- | --- |
| Iron | ppm | █ 3 | █ 17 | --- | --- |
| Copper | ppm | 0 | 3 | --- | --- |
| Lead | ppm | 0 | 0 | --- | --- |
| Tin | ppm | 0 | 0 | --- | --- |
| Aluminum | ppm | 0 | 2 | --- | --- |
| Chromium | ppm | █ 0 | █ <1 | --- | --- |
| Molybdenum | ppm | █ 0 | █ <1 | --- | --- |
| Nickel | ppm | █ 0 | █ <1 | --- | --- |
| Titanium | ppm | 0 | 0 | --- | --- |
| Silver | ppm | 0 | 0 | --- | --- |
| Manganese | ppm | █ 0 | █ <1 | --- | --- |
| Vanadium | ppm | 0 | 0 | --- | --- |

ADDITIVES

| | | | | | |
|------------|-----|--------------|--------|-----|-----|
| Calcium | ppm | █ 51 | █ 16 | --- | --- |
| Magnesium | ppm | █ 3 | 22 | --- | --- |
| Zinc | ppm | █ 25 | █ 13 | --- | --- |
| Phosphorus | ppm | █ 747 | █ 1399 | --- | --- |
| Barium | ppm | █ 0 | █ 0 | --- | --- |
| Boron | ppm | █ 5 | █ 345 | --- | --- |

COASTAL CAROLINA YACHT SALES

145 LOCKWOOD BLVD

CHARLESTON, SC

US 29403

Contact: STEVE VASAS

steve@ccyachtsales.com

T:

F:

Diagnosis

Resample at the next service interval to monitor. Please note that this is a corrected copy for laboratory data updates. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP568144

Unique No: 10729112

Signed: Sean Felton

Report Date: 09 Nov 2023

OIL ANALYSIS REPORT

**VOLVO
PENTA**

GRAPHS

