



TIM HAGEN VOLVO PENTA A560887 - PORT DIESEL ENGINE

Sample No: VPA056909

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
		\(\text{DA 05 C000}\)		
Sample Number		VPA056909	 	
Sample Date		08 Nov 2023	 	
Machine Hours		0	 	
Oil Hours		200	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	14.4	 	
Base Number (BN)	mg KOH/g	■8.1	 	
Oxidation (PA)	%	79	 	
` '	,,,			
CONTAMINATION				
Soot %	%	■0.3	 	
Nitration (PA)	%	79	 	
Sulfation (PA)	%	60	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon		■3		
	ppm			
Sodium	ppm	■ <1	 	
Potassium	ppm	5	 	
WEAR METALS				
Iron	ppm	■10	 	
Copper	ppm	4	 	
Lead	ppm	■<1	 	
Tin	ppm	□ <1	 	
Aluminum	ppm	1	 	
Chromium	ppm		 	
Molybdenum		12	 	
	ppm	_		
Nickel	ppm	■ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	■0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	1943	 	
Magnesium	ppm	■239	 	
Zinc	ppm	1274	 	
Phosphorus	ppm	1039	 	
Barium	ppm	□0	 	
Boron	ppm	114	 	
	- P			

Aqua Yacht Harbor Marina

3832 Hwy. 25 North, 3832 Hwy. 25 North IUKA, MS
US 38852
Contact: DENNIS KANIZAI dkanizai@shmarinas.com

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP299833Unique No:10741278Signed:Don BaldridgeReport Date:16 Nov 2023

OIL ANALYSIS REPORT



