



## GREG SHALER 502336 ZF 51220253796 - INBOARD - CENTER GEARBOX

Sample No: VPA058264

Oil Type: CHEVRON SYN ATF HD

SAMPLE INFORM	ATION .			
24MFLE INFURM	ATION			
Sample Number		VPA058264	 	
Sample Date		13 Nov 2023	 	
Machine Hours		974	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	■30.1	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	<b>■</b> 3	 	
Sodium	ppm	■0	 	
Potassium	ppm	■0	 	
WEAR METALS				
PQ		<b>18</b>	 	
Iron	ppm	<b>2</b>	 	
Copper	ppm	<b>-&lt;</b> 1	 	
Lead	ppm	■0	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>■</b> 0	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■&lt;1</b>	 	
Vanadium	ppm	0	 	
ADDITIDES				
Calcium	ppm	<b>7</b> 4	 	
Magnesium	ppm	<1	 	
Zinc	ppm	■0	 	
Phosphorus	ppm	■220	 	
Barium	ppm	■0	 	
Boron	ppm	■106	 	

## **North Harbor Diesel Inc**

720 30Th Street ANACORTES, WA US 98221 Contact: ROBBIN MURDOCK robbin@northharbordiesel.com T: (360)299-1904 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP179089Unique No:10753434Signed:Don BaldridgeReport Date:24 Nov 2023

## OIL ANALYSIS REPORT



