

OIL ANALYSIS REPORT

VOLVO PENTA

SEA WOLF SEA WOLF VOLVO PENTA 7011415895 - PORT GEARBOX

Sample No: VPA036210

Oil Type: NOT GIVEN

SAMPLE INFORMATION

Sample Number	VPA036210	---	---	---
Sample Date	15 Nov 2023	---	---	---
Machine Hours	304	---	---	---
Oil Hours	304	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

MARINE DIESEL SERVICES INC
1711 WHITTIER AVE, SUITE B
COSTA MESA, CA
US 92627
Contact: BEN ALMAZAN
marinedieselservices@outlook.com
T: (949)612-8180
F: x:

OIL CONDITION

Visc @ 40°C	cSt	■ 89.7	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	■ NEG	---	---	---
Silicon	ppm	■ 6	---	---	---
Sodium	ppm	■ <1	---	---	---
Potassium	ppm	■ 2	---	---	---

WEAR METALS

PQ		■ 5	---	---	---
Iron	ppm	■ 7	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 60	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 0	---	---	---
Vanadium	ppm	■ 0	---	---	---

ADDITIVES

Calcium	ppm	■ 1071	---	---	---
Magnesium	ppm	■ 951	---	---	---
Zinc	ppm	■ 1227	---	---	---
Phosphorus	ppm	■ 1043	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ <1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP288530
Unique No: 10754565
Signed: Jonathan Hester
Report Date: 27 Nov 2023

OIL ANALYSIS REPORT



GRAPHS

