



## KOHLER 0677429 - GENSET

Sample No: VPA045596
Oil Type: NOT GIVEN

SAMPLE INFORMAT	TION			
		VPA045596		
Sample Number Sample Date		20 Nov 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
_		NORMAL	 	
Sample Status		NORWIAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>14.0</b>	 	
Base Number (BN)	mg KOH/g	■9.5	 	
Oxidation (PA)	%	66	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	<b>■</b> 0.1	 	
Nitration (PA)	%	56	 	
Sulfation (PA)	%	55	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon		<b>□</b> 7	 	
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	<b>1</b>	 	
	ppm	•		
WEAR METALS				
Iron	ppm	<b>3</b>	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	45	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	<1	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	1557	 	
Magnesium	ppm	528	 	
Zinc	ppm	1292	 	
Phosphorus	ppm	970	 	
Barium	ppm	0	 	
Boron	ppm	48	 	

## **Aqua Yacht Harbor Marina**

3832 Hwy. 25 North, 3832 Hwy. 25 North IUKA, MS
US 38852
Contact: DENNIS KANIZAI
dkanizai@shmarinas.com

F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP299833Unique No:10755182Signed:Jonathan HesterReport Date:27 Nov 2023





