

OIL ANALYSIS REPORT

VOLVO PENTA

POLSTER VOLVO PENTA POLSTER (S/N NOT GIVEN) - STARBOARD IPS

Sample No: VPA057457
Oil Type: GEAR OIL SAE 75W90

SAMPLE INFORMATION

Sample Number	VPA057457	---	---	---
Sample Date	26 Nov 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

BAY MARINE

3 E MADISON ST
WAUKEGAN, IL
US 60085
Contact: BRENDAN COWHEY
brendan@baymarine.net
T: (847)336-2628
F:

OIL CONDITION

Visc @ 40°C	cSt	█ 100	---	---	---
-------------	-----	-------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	2	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ <1	---	---	---

WEAR METALS

PQ		█ 5	---	---	---
Iron	ppm	█ 20	---	---	---
Copper	ppm	6	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	█ 108	---	---	---
Magnesium	ppm	61	---	---	---
Zinc	ppm	█ 50	---	---	---
Phosphorus	ppm	█ 1435	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 322	---	---	---

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is suitable for further service.

Depot: VP1174336
Unique No: 10762946
Signed: Sean Felton
Report Date: 29 Nov 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

