



JOHN BYRE 6422 NORTHERN LIGHTS M8441W23 8442-41852C - PORT GENSET

Sample No: VPA060168
Oil Type: NOT GIVEN

SAMPLE INFORMAT	TION			
		VD4060160		
Sample Number		VPA060168 22 Nov 2023	 	
Sample Date Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		Not Changd NORMAL		
Sample Status		NORWAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	14.0	 	
Base Number (BN)	mg KOH/g	8.7	 	
Oxidation (PA)	%	49	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	0	 	
Nitration (PA)	%	51	 	
Sulfation (PA)	%	48	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon Sodium	ppm	4	 	
Potassium	ppm	□ 1 □ 4	 	
FOLASSIUIII	ppm		 	
WEAR METALS				
Iron	ppm	□ <1	 	
Copper	ppm	■0	 	
Lead	ppm	■0	 	
Tin	ppm	■0	 	
Aluminum	ppm	2	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	6	 	
Nickel	ppm	■<1	 	
Titanium	ppm	0	 	
Silver	ppm	■ 0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	1184	 	
Magnesium	ppm	731	 	
Zinc	ppm	848	 	
Phosphorus	ppm	723	 	
Barium	ppm	0	 	
Boron	ppm	82	 	

Northwest Diesel Power

1325 ROEDER AVE SUITE 103
BELLINGHAM, WA
US 98225
Contact: BRANDON ROBERTSON
parts@nwdieselpower.com
T:
F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP759009Unique No:10765414Signed:Don BaldridgeReport Date:03 Dec 2023

OIL ANALYSIS REPORT



