OIL ANALYSIS REPORT

VOLVO PENTA 3940019648 - PORT IPS

Sample No:	VPA056836
Oil Type:	NOT GIVEN

SAMPLE INFORMATION Sample Number VPA056836 28 Nov 2023 Sample Date Machine Hours 683 0 **Oil Hours** N/A Oil Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 103 CONTAMINATION % Water NEG Silicon ppm 15 Sodium 6 🔲 ppm Potassium ppm 0 WEAR METALS PO 17 36 Iron ppm Copper ppm 14 Lead 0 ppm 0 Tin ppm Aluminum ppm <1 Chromium □ <1 ppm Molybdenum 0 ppm **||** <1 Nickel ppm Titanium 0 ppm Silver 0 ppm Manganese 1 ppm Vanadium 0 ppm **ADDITIVES** Calcium 24 ppm 5 Magnesium ppm Zinc ppm 10 Phosphorus ppm 1437 Barium 0 ppm



JOHNSTONS MARINE SERVICES

1850 NW 15th AVENUE, SUITE 205 POMPANO BEACh, FL US 33069 Contact: NEIL JOHNSTON neil@1jms.com T: (984)448-0813 F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VPJOHDEE

 Unique No:
 10766682

 Signed:
 Angela Borella

 Report Date:
 04 Dec 2023

ppm

Boron


285

Contact/Location: NEIL JOHNSTON - VPJOHDEE

OIL ANALYSIS REPORT



GRAPHS



Report Id: VPJOHDEE [WUSCAR] 06022182 (Generated: 12/04/2023 14:12:04) Rev: 1

Contact/Location: NEIL JOHNSTON - VPJOHDEE