



## MURPHY GIRL 10072 H51973 - CENTER DIESEL ENGINE

Sample No: VPA058426

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA058426	 	
Sample Date		27 Nov 2023	 	
Machine Hours		852	 	
Oil Hours		21	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>■13.1</b>	 	
Base Number (BN)	mg KOH/g	■8.5	 	
Oxidation (PA)	%	59	 	
CONTAMINATION				
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■0.1	 	
Nitration (PA)	%	48	 	
Sulfation (PA)	%	52	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>■</b> 2	 	
Sodium	ppm	<b>■</b> 5	 	
Potassium	ppm	<b>4</b>	 	
WEAR METALS				
Iron	ppm	<b>■</b> 3	 	
Copper	ppm	■3	 	
Lead	ppm	■0	 	
Tin	ppm	0	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	24	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	■0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■</b> 0	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	10 10 100	<b>2293</b>		
Magnesium	ppm	■2293 ■38	 	
_	ppm	■ 1338		
Zinc	ppm		 	
Phosphorus Barium	ppm	<b>■</b> 1099		
Boron	ppm	<b>■</b> 0 <b>■</b> 152	 	
DUIUII	ppm	<b>152</b>	 	

## The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD US 21654 Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899 F: x:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP592286Unique No:10767895Signed:Sean FeltonReport Date:05 Dec 2023

## **OIL ANALYSIS REPORT**



