

OIL ANALYSIS REPORT

VOLVO PENTA

CHRIS HERMAN CARVER C34 V-DRIVE - INBOARD (S/N NOT GIVEN) - STARBOARD GEARBOX

Sample No: VPA056535

Oil Type: DEXRON III

SAMPLE INFORMATION

Sample Number	VPA056535	---	---	---
Sample Date	01 Dec 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

WEST COAST YACHTS

2600 NEWPORT BLVD, SUITE 122
NEWPORT BEACH, CA
US 92663
Contact: CHRIS HERMAN
chris@wcyachts.com
T: (714)329-4138
F:

OIL CONDITION

Visc @ 40°C	cSt	█ 26.5	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---

WEAR METALS

PQ		█ 36	---	---	---
Iron	ppm	█ 41	---	---	---
Copper	ppm	█ 17	---	---	---
Lead	ppm	█ 10	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	█ 0	---	---	---

ADDITIVES

Calcium	ppm	█ 87	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 25	---	---	---
Phosphorus	ppm	█ 215	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 115	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VPWESNEW
Unique No: 10768650
Signed: Angela Borella
Report Date: 06 Dec 2023

OIL ANALYSIS REPORT



GRAPHS

