OIL ANALYSIS REPORT

@VENTURE EIA 3205002011 - INBOARD - STARBOARD GEARBOX

Sample No: VPA058425

Oil Type: SHELL ROTELLA T 30

SAMPLE INFORMATION

						A
Sample Number		VPA058425				T I T I : A
Sample Date		01 Dec 2023				The Talaria Company
Machine Hours		633				202 Banks St., One Little Harbor Landing
Oil Hours		68				OXFORD, MD
Oil Changed		Changed				US 21654
Sample Status		NORMAL				Contact: TRACY PELLERIN
						tpellerin@hinckleyyachts.com
OIL CONDITION						T: (410)770-4899
Visc @ 40°C	cSt	91.7				F: x:
CONTAMINATIO	N					Diagnosis
LUNTAMINATIU	N					
Water	%	NEG				Resample at the next service interval to monitor.All component wear rates
Silicon	ppm	4				are normal. There is no indication of
Sodium	ppm	3				any contamination in the oil. The
Potassium	ppm	0				condition of the oil is acceptable for
WEAR METALS						the time in service.
PQ		11				
Iron	ppm	2				
Copper	ppm	71				
Lead	ppm	0				
Tin	ppm	0				
Aluminum	ppm	2				
Chromium	ppm	 <1				
Molybdenum	ppm	111				
Nickel	ppm	0				
Titanium	ppm	0				
Silver	ppm	0				
Manganese	ppm	 <1				
Vanadium	ppm	0				
ADDITIVES						
Calcium	ppm	2529				_
Magnesium	ppm	50				
Zinc	ppm	1136				
Phosphorus	ppm	<u> </u>				
Barium	ppm	0				
Boron	ppm	8				



 Depot:
 VP592286

 Unique No:
 10779516

 Signed:
 Jonathan Hester


 Report Date:
 14 Dec 2023

Contact/Location: TRACY PELLERIN - VP592286

OIL ANALYSIS REPORT



GRAPHS



Contact/Location: TRACY PELLERIN - VP592286