

OIL ANALYSIS REPORT

VOLVO PENTA

DEAN WALUND 5025571 VOLVO PENTA 51220267587 - INBOARD - GEARBOX

Sample No: VPA059139

Oil Type: CHEVRON AUTOMATIC TRANS FLUID MD-3

SAMPLE INFORMATION

Sample Number	VPA059139	---	---	---
Sample Date	05 Dec 2023	---	---	---
Machine Hours	991	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

Endor Marine LLC - Coastal Marine - 152124
4300 11th Ave. NW
SEATTLE, WA
US 98107
Contact: WILLOW YANARELLA
service@coastalmarineengine.com
T: (206)784-3703
F: (206)784-8823

OIL CONDITION

Visc @ 40°C	cSt	█ 26.4	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 2	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 0	---	---	---

WEAR METALS

PQ		█ 22	---	---	---
Iron	ppm	█ 14	---	---	---
Copper	ppm	█ 16	---	---	---
Lead	ppm	█ 1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	7	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 158	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 62	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP794951
Unique No: 10782712
Signed: Sean Felton
Report Date: 15 Dec 2023

OIL ANALYSIS REPORT



GRAPHS

