

Report Id: VP509836 [WUSCAR] 06038131 (Generated: 12/21/2023 00:19:48) Rev: 1



## VOLVO PENTA 3950005362 - CENTER IPS

Sample No: VPA028087
Oil Type: NOT GIVEN

CAMPLE INFARM	ATION			_
SAMPLE INFORM	ATIUN			
Sample Number		VPA028087	 	
Sample Date		13 Dec 2023	 	
Machine Hours		300	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>103</b>	 	
CONTAMINATION	1			
Water	%	NEG	 	
Silicon	ppm	4	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR METALS				
PQ		■20	 	
Iron	ppm	<b>■</b> 26	 	
Copper	ppm	4	 	
Lead	ppm	0	 	
Tin	ppm	<1	 	
Aluminum	ppm	1	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	14	 	
Magnesium	ppm	84	 	
Zinc	ppm	7	 	
Phosphorus	ppm	1408	 	
Barium	ppm	0	 	
Boron	ppm	371	 	

## Diesel Services of America, Inc.

2501 West State Road 84 FORT LAUDERDALE, FL US 33312 Contact: Dan Rosas dan@dieselservicesofamerica.com

1: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP509836Unique No:10793360Signed:Don BaldridgeReport Date:20 Dec 2023





