

OIL ANALYSIS REPORT

VOLVO PENTA

MARLENE A130440062 - GENSET

Sample No: VPA060759

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMATION

Sample Number	VPA060759	VPA044198	---	---
Sample Date	08 Dec 2023	27 Dec 2022	---	---
Machine Hours	91	73	---	---
Oil Hours	18	10	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

OIL CONDITION

Visc @ 100°C	cSt	█ 12.9	█ 12.8	---	---
Base Number (BN)	mg KOH/g	█ 7.3	█ 8.3	---	---
Oxidation (PA)	%	67	67	---	---

CONTAMINATION

Water	%	NEG	NEG	---	---
Soot %	%	█ 0.1	█ 0.1	---	---
Nitration (PA)	%	43	47	---	---
Sulfation (PA)	%	56	56	---	---
Glycol	%	NEG	NEG	---	---
Fuel	%	<1.0	<1.0	---	---
Silicon	ppm	█ 4	█ 4	---	---
Sodium	ppm	█ 1	█ 2	---	---
Potassium	ppm	█ 8	█ 6	---	---

WEAR METALS

Iron	ppm	█ 2	█ 6	---	---
Copper	ppm	█ 0	█ <1	---	---
Lead	ppm	█ 0	█ <1	---	---
Tin	ppm	█ <1	█ <1	---	---
Aluminum	ppm	█ 2	█ 2	---	---
Chromium	ppm	█ 0	█ <1	---	---
Molybdenum	ppm	█ 0	█ <1	---	---
Nickel	ppm	█ <1	█ 0	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	█ <1	█ 0	---	---
Manganese	ppm	█ <1	█ <1	---	---
Vanadium	ppm	<1	0	---	---

ADDITIVES

Calcium	ppm	█ 1988	█ 2095	---	---
Magnesium	ppm	█ 16	█ 13	---	---
Zinc	ppm	█ 1099	█ 1039	---	---
Phosphorus	ppm	█ 964	█ 909	---	---
Barium	ppm	█ 0	█ 0	---	---
Boron	ppm	█ 197	█ 192	---	---

The Talaria Company

202 Banks St., One Little Harbor Landing
OXFORD, MD

US 21654

Contact: TRACY PELLERIN

tpellerin@hinckleyyachts.com

T: (410)770-4899

F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP592286

Unique No: 10794171

Signed: Sean Felton

Report Date: 20 Dec 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

