

OIL ANALYSIS REPORT

**VOLVO
PENTA**

AONBHARR 10072 20084277 - INBOARD - PORT GEARBOX

Sample No: VPA047806

Oil Type: SHELL ROTELLA T 30

SAMPLE INFORMATION

Sample Number	VPA047806	---	---	---
Sample Date	12 Dec 2023	---	---	---
Machine Hours	1110	---	---	---
Oil Hours	26	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 40°C	cSt	■ 87.0	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	■ NEG	---	---	---
Silicon	ppm	■ 4	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 2	---	---	---

WEAR METALS

PQ		■ 15	---	---	---
Iron	ppm	■ 22	---	---	---
Copper	ppm	■ 50	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 3	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 117	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	■ <1	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	■ 2779	---	---	---
Magnesium	ppm	■ 25	---	---	---
Zinc	ppm	■ 1228	---	---	---
Phosphorus	ppm	■ 1121	---	---	---
Barium	ppm	■ 9	---	---	---
Boron	ppm	■ 8	---	---	---

The Talaria Company

202 Banks St., One Little Harbor Landing
OXFORD, MD

US 21654

Contact: TRACY PELLERIN

tpellerin@hinckleyyachts.com

T: (410)770-4899

F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP592286

Unique No: 10794847

Signed: Angela Borella

Report Date: 21 Dec 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

