



## SMART DIESEL SERVICE LLC 1758 ONAN 1180406568 - CENTER GENSET

Sample No: VPA042127

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA042127	 	
Sample Date		19 Dec 2023	 	
Machine Hours		1366	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>14.17</b>	 	
Base Number (BN)	mg KOH/g	■9.0	 	
Oxidation (PA)	%	67	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	NEG ■ 0.1	 	
Nitration (PA)	%	57	 	
Sulfation (PA)	%	57	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■8	 	
Sodium	ppm	■3	 	
Potassium	ppm	<b>2</b>	 	
WEAR METALS				
Iron	ppm	7	 	
Copper	ppm	7	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	■39	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	■0	 	
Manganese	ppm	<b>■ &lt;1</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>1264</b>	 	
Magnesium	ppm	<b>665</b>	 	
Zinc	ppm	■ 885	 	
Phosphorus	ppm	<b>714</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>43</b>	 	

## **SMART DIESEL SERVICE**

102 NW 133RD AVE, UNIT 103 PLANTATION, FL US 33325 Contact: ANDRES GARMENDIA smartdieselservice@gmail.com T: (954)258-8100 F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN level is low. The condition of the oil is acceptable for the time in service.

Depot:VPSMAPLAUnique No:10796237Signed:Doug BogartReport Date:20 Dec 2023

## **OIL ANALYSIS REPORT**



