



## GREENBERG 500-87 VOLVO PENTA 3940014264 - PORT IPS

Sample No: VPA021862
Oil Type: {unknown}

SAMPLE INFORMA	ATION			
Sample Number		VPA021862	 	
Sample Date		21 Nov 2023	 	
Machine Hours		1121	 	
Oil Hours		0		
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	<b>106</b>	 	
CONTAMINATION				
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	<1	 	
Sodium	ppm	<b>■&lt;1</b>	 	
Potassium	ppm	<b>■</b> 0	 	
WEAR METALS				
PQ		<b>12</b>	 	
Iron	ppm	<b>24</b>	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	<1	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	1	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	0	 	
Magnesium	ppm	0	 	
Zinc	ppm	0	 	
Phosphorus	ppm	1310	 	
Barium	ppm	0	 	
Boron	ppm	304	 	

## **Outstanding Marine**

PO Box 274
GALENA, MD
US 21635
Contact: Ronda Bolinger rlwb@verizon.net
T:
F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP153685Unique No:10816458Signed:Doug BogartReport Date:04 Jan 2024

## **OIL ANALYSIS REPORT**



