



GRANT GRANT VOLVO PENTA GRANT - GENSET

Sample No: VPA058300
Oil Type: {unknown}

SAMPLE INFORMAT	TION			
Sample Number		VPA058300		
Sample Date		03 Jan 2024		
Machine Hours		0 3 3 3 3 1 2 0 2 4		
Oil Hours		0		
Oil Changed		N/A		
Sample Status		NORMAL		
		TOTAL DE	_	
OIL CONDITION				
Visc @ 100°C	cSt	12.6		
Base Number (BN)	mg KOH/g	■9.0		
Oxidation (PA)	%	63		
CONTAMINATION				
Water	%	NEG		
Soot %	%	NEG ■ 0.2		
Nitration (PA)	%	54		
Sulfation (PA)	%	60		
Glycol	%	NEG		
Fuel	%	<1.0		
Silicon	ppm	■9		
Sodium	ppm	0		
Potassium	ppm	2		
	la la			
WEAR METALS				
Iron	ppm	12		
Copper	ppm	2		
Lead	ppm	■ <1		
Tin	ppm	■<1		
Aluminum	ppm	4		
Chromium	ppm	■<1		
Molybdenum	ppm	100		
Nickel	ppm	■<1		
Titanium	ppm	<1		
Silver	ppm	■ 0		
Manganese	ppm	<1		
Vanadium	ppm	<1		
ADDITIDDA				
Calcium	ppm	1809		
Magnesium	ppm	546		
Zinc	ppm	861		
Phosphorus	ppm	766		
Barium	ppm	11		
Boron	ppm	268		

Harry's Marine Service LLC

1141 N. Citrus St.
Orange, CA
US 92887
Contact: TARAH AULD
info@harrysmarine.com
T: (714)771-7899
F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP867279Unique No:10817244Signed:Doug BogartReport Date:04 Jan 2024

OIL ANALYSIS REPORT



