



## HUCKLEBERRY PB 2B690891 - STARBOARD GASOLINE ENGINE

Sample No: VPA058147

Oil Type: MERCURY 25W50

SAMPLE INFORMA	TION			
Sample Number		VPA058147	VPA025358	 
Sample Date		01 Nov 2023	02 May 2022	 
Machine Hours		0	0	 
Oil Hours		0	0	 
Oil Changed		Changed	Not Changd	 
Sample Status		SEVERE	ABNORMAL	 
		JEVERE	ADNONWAL	 
OIL CONDITION				
Visc @ 100°C	cSt	<b>10.0</b>	<b>11.8</b>	 
Base Number (BN)	mg KOH/g	■8.6	12.0	 
Oxidation (PA)	%	15	14	 
CONTAMINATION				
Water	%	NEG	<b>△</b> 0.680	 
Soot %	%	MLG	0.000	 
Nitration (PA)	%	10	9	 
Sulfation (PA)	%	11	9	 
Glycol	%	NEG	NEG	 
Fuel	%	10.0	<1.0	 
Silicon		■ 17	□ 11	 
Sodium	ppm	■ 17 ■ <1	7	 
Potassium	ppm	<b>1</b>	0	 
	ррпп			
WEAR METALS				
Iron	ppm	<b>11</b>	■8	 
Copper	ppm	<b>■</b> 4	■3	 
Lead	ppm	<b>2</b>	<b>1</b>	 
Tin	ppm	■1	<b>5</b>	 
Aluminum	ppm	<b>6</b>	<b>7</b>	 
Chromium	ppm	<b>■&lt;1</b>	<b>0</b>	 
Molybdenum	ppm	45	45	 
Nickel	ppm	<b>■</b> 0	<b></b> <1	 
Titanium	ppm	0	<1	 
Silver	ppm	■0	<b>-</b> <1	 
Manganese	ppm	2	<1	 
Vanadium	ppm	0	0	 
ADDITIVES	ppm			
		4004	24.60	
Calcium	ppm	1921	2160	 
Magnesium 	ppm	10	38	 
Zinc	ppm	790	846	 
Phosphorus	ppm	689	736	 
Barium	ppm	0	0	 
Boron	ppm	130	227	 

## The Talaria Company

202 Banks St., One Little Harbor Landing OXFORD, MD US 21654 Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899 F: x:

## Diagnosis

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.

Depot:VP592286Unique No:10830429Signed:Doug BogartReport Date:29 Jan 2024

## **OIL ANALYSIS REPORT**



