## **OIL ANALYSIS REPORT**

### RICHARD RAMAGLIA TOM ZF 45229N - INBOARD - PORT GEARBOX

Sample No: VPA036590

Oil Type: VOLVO PENTA ATF

#### SAMPLE INFORMATION

Sample Number		VPA036590	 	
Sample Date		12 Jan 2024	 	
Machine Hours		298	 	 2775 KURTZ ST, STE 12
Oil Hours		0	 	 SAN DIEGO, CA
Oil Changed		N/A	 	 US 92110
Sample Status		NORMAL	 	 Contact: Terry Albee
				TALBEE@ADMIRALTYMARINE.NET
OIL CONDITION				T:
Visc @ 40°C	cSt	26.9	 	 F:
CONTAMINATION				Diagnosis
Water	%	NEG	 	 Resample at the next service inter
Silicon	ppm	6	 	 to monitor.All component wear ra are normal. There is no indication
Sodium	ppm	0	 	 any contamination in the compon
Potassium	ppm	0	 	 The condition of the oil is accepta
WEAR METALS				for the time in service.
PQ		35	 	
Iron	ppm	31	 	
Copper	ppm	52	 	
Lead	ppm	44	 	
Tin	ppm	0	 	
Aluminum	ppm	3	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	11	 	
Magnesium	ppm	2	 	
Zinc	ppm	35	 	
Phosphorus	ppm	151	 	
Barium	ppm	63	 	
Boron	ppm	48	 	



 Depot:
 VP151529

 Unique No:
 10832881

 Signed:
 Don Baldridge


 Report Date:
 17 Jan 2024

Contact/Location: Terry Albee - VP151529

# **OIL ANALYSIS REPORT**



#### GRAPHS



Report Id: VP151529 [WUSCAR] 06061499 (Generated: 01/18/2024 03:31:53) Rev: 1

Contact/Location: Terry Albee - VP151529