OIL ANALYSIS REPORT

JOHN MCINTOSH YANMAR JOHN MCINTOSH (S/N NOT GIVEN) - PORT GEARBOX

Sample No:VPA058079Oil Type:{unknown}

SAMPLE INFORMATION

Sample Number Sample Date Machine Hours		VPA058079	 	
				MELBOURNE MARINE DIESEL
Machine Hours		15 Jan 2024	 	
		0	 	 MELBOURNE, FL
Oil Hours		0	 	 US
Oil Changed		N/A	 	 Contact: SERVICE MANAGER
Sample Status		NORMAL	 	 info@melbournemarinediesel.com
OIL CONDITION				T: (321)425-2517 F:
Visc @ 40°C	cSt	80.05	 	
CONTAMINATION				Diagnosis
Water	%	NEG	 	 No corrective action is recommended
	ppm	8	 	 at this time. Resample at the next
		2	 	 service interval to monitor.All
	ppm ppm	0	 	 component wear rates are normal. There is no indication of any
FOLASSIUITI	ррп	0	 	 contamination in the oil. The
WEAR METALS				condition of the oil is acceptable for
PQ		79	 	 the time in service.
	ppm	54	 	
	ppm	_ _ 17	 	
	ppm	3	 	
Tin p	ppm	■<1	 	
	ppm	2	 	
	ppm	0	 	
	ppm	82	 	
	ppm	0	 	
	ppm	0	 	
	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium p	ppm	0	 	
ADDITIVES				
Calcium	ppm	1110	 	
	ppm	541	 	
Zinc 🛛	ppm	793	 	
Phosphorus p	ppm	752	 	
Barium p	ppm	0	 	
Boron	ppm	178	 	

 Depot:
 VP1222400

 Unique No:
 10832989

 Signed:
 Doug Bogart

 Report Date:
 16 Jan 2024


Contact/Location: SERVICE MANAGER - VP1222400



OIL ANALYSIS REPORT



GRAPHS



Report Id: VP1222400 [WUSCAR] 06061607 (Generated: 01/16/2024 16:18:56) Rev: 1

Contact/Location: SERVICE MANAGER - VP1222400