



## TREVOR SKELLY 7718151 ZF 95-15031 - INBOARD (S/N 96-15031) - STARBOARD GEARBOX

Sample No: VPA060841

Oil Type: CHEVRON DELO 400 SAE 30

CAMPLE INCORN	ATION			
SAMPLE INFORM	MATIUN			
Sample Number		VPA060841	VPA033467	 
Sample Date		09 Jan 2024	28 Feb 2022	 
Machine Hours		1710	1388	 
Oil Hours		310	200	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	ATTENTION	 
OIL CONDITION				
Visc @ 40°C	cSt	<b>75.1</b>	95.4	 
CONTAMINATIO	N			
Water	%	NEG	NEG	 
Silicon	ppm	<b>4</b>	<b>5</b>	 
Sodium	ppm	<b>3</b>	<b>2</b>	 
Potassium	ppm	<b>■</b> 0	□0	 
WEAR METALS				
PQ		<b>1</b> 6	<b>□</b> 19	 
Iron	ppm	<u> </u>	44	 
Copper	ppm	<b>■</b> 28	<b>1</b> 22	 
Lead	ppm	■36	<b>1</b> 16	 
Tin	ppm	<b>■&lt;1</b>	<b>■</b> 9	 
Aluminum	ppm	<b>2</b>	<b>4</b>	 
Chromium	ppm	<b>0</b>	<1	 
Molybdenum	ppm	<b>65</b>	■87	 
Nickel	ppm	<b>0</b>	<1	 
Titanium	ppm	0	0	 
Silver	ppm	0	1	 
Manganese	ppm	<b>■</b> 0	<b>-</b> <1	 
Vanadium	ppm	0	0	 
ADDITIVES				
Calcium	ppm	<b>1111</b>	<b>□</b> 1187	 
Magnesium	ppm	<b>960</b>	■833	 
Zinc	ppm	<b>■</b> 1182	□1085	 
Phosphorus	ppm	<b>1102</b>	1023	 
Barium	ppm	■0	0	 
Boron	ppm	<b>45</b>	217	 
	P P ' ' ' '			

## Pacific Power Group - VP981534

7215 S 228th St Kent, WA US 98032 Contact: PAT RYAN pryan@pacificpowergroup.com T: (253)520-5163 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP99031103

 Unique No:
 10834491

 Signed:
 Sean Felton

 Report Date:
 18 Jan 2024

## **OIL ANALYSIS REPORT**



