



BILL MORENO - GALEON VOLVO PENTA VP3 18230 - STARBOARD DIESEL ENGINE

Sample No: VPA036704

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION				
Sample Number		VPA036704	VPA043421		
Sample Date		19 Dec 2023	10 Dec 2022		
Machine Hours		566	513		
Oil Hours		566	513		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	ATTENTION		
·			711121111011	_	
OIL CONDITION					
Visc @ 100°C	cSt	13.2	1 2.3		
Base Number (BN)	mg KOH/g	■8.5	5.9		
Oxidation (PA)	%	64	129		
CONTAMINATION					
Water	%	NEG	NEG		
Soot %	%	MEG ■ 0.2	□2.5		
Nitration (PA)	%	52	125		
Sulfation (PA)	%	56	88		
Glycol	%	NEG	NEG		
Fuel	%	<1.0	1.2		
Silicon	ppm	4	7		
Sodium	ppm	1	0		
Potassium	ppm	<u> </u>	1		
WEAR METALS					
		=3			
Iron	ppm	3	9		
Copper	ppm	2 1	□ 68		
Lead Tin	ppm	■ 1	□2 □<1		
Aluminum	ppm	■<1	<u>1</u> 1		
Chromium	ppm	_	<1		
Molybdenum	ppm	□ <1 □ 10	□ 58		
Nickel	ppm	■ 10 ■ <1	<1		
Titanium	ppm	■0	0		
Silver	ppm	0	1		
Manganese	ppm	■0	< 1		
Vanadium	ppm	<1	<1		
ADDITIVES					
		=1040	= 1074		
Calcium	ppm	1849	□ 1071		
Magnesium	ppm	147	■876 ■1181		
Zinc	ppm	■ 1140 ■ 075	□1181 □200		
Phosphorus Barium	ppm	■ 975	□ 990		
Boron	ppm	□ 0 □ 137	0 3		
DOTOIT	ppm	137			

Larry's Lighthouse Marina

1250

AQUEBOGUE, NY US 11931

Contact: MAX FUHLBRUGGE info@lighthousemarina.com

T: x: F: x:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP610438Unique No:10843059Signed:Angela BorellaReport Date:23 Jan 2024

OIL ANALYSIS REPORT



