



## GAMBARDELLA 7551 VOLVO PENTA 3200005641 - PORT IPS

Sample No: VPA059582

**Oil Type:** VOLVO API GL-5 SAE 75W90

SAMPLE INFORM	IATION			
Sample Number		VPA059582		 
Sample Date		10 Jan 2024		 
Machine Hours		71		 
Oil Hours		71		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
	_	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_	
OIL CONDITION				
Visc @ 40°C	cSt	<b>■96.4</b>		 
CONTAMINATION	N			
Water	%	NEG		 
Silicon	ppm	5		 
Sodium	ppm	<b>4</b>		 
Potassium	ppm	■8		 
WEAR METALS				
PQ		<b>17</b>		 
Iron	ppm	<b>27</b>		 
Copper	ppm	<b>11</b>		 
Lead	ppm	<1		 
Tin	ppm	<1		 
Aluminum	ppm	2		 
Chromium	ppm	<b>■&lt;1</b>		 
Molybdenum	ppm	<b>■&lt;1</b>		 
Nickel	ppm	<b>1</b>		 
Titanium	ppm	<1		 
Silver	ppm	0		 
Manganese	ppm	<b>4</b>		 
Vanadium	ppm	0		 
ADDITIVES				
Calcium	ppm	<b>■</b> 27		 
Magnesium	ppm	 ■887		 
Zinc	ppm	<b>■</b> <1		 
Phosphorus	ppm	<b>1528</b>		 
Barium	ppm	■0		 
Boron	ppm	<b>■</b> 574		 

## Strongs Water Club & Marina LLC

PO BOX 1409 MATTITUCK, NY US 11952 Contact: JAN SCHARWACHTER jan@strongsmarine.com

T: (631)298-4739 F: (631)298-4803

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP930782Unique No:10847394Signed:Don BaldridgeReport Date:28 Jan 2024

## **OIL ANALYSIS REPORT**



