

# OIL ANALYSIS REPORT

# VOLVO PENTA

**JOE BARBARETTA ZF 143533-331200 - INBOARD - STARBOARD GEARBOX**

**Sample No:** VPA049989

**Oil Type:** ATF

## SAMPLE INFORMATION

Sample Number	VPA049989	---	---	---
Sample Date	09 Feb 2024	---	---	---
Machine Hours	423	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

## YACHT BASIN MARINA

1866 OTTAWA BEACH RD

HOLLAND, MI

US 49424

Contact: OIL SAMPLE/PART

kyle@yachtbasinmarina.com

T: (616)786-2205

F:

## OIL CONDITION

Visc @ 40°C	cSt	█ 21.9	---	---	---
-------------	-----	--------	-----	-----	-----

## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 17	---	---	---
Sodium	ppm	█ 10	---	---	---
Potassium	ppm	█ 7	---	---	---

## WEAR METALS

PQ		█ 17	---	---	---
Iron	ppm	█ 62	---	---	---
Copper	ppm	█ 332	---	---	---
Lead	ppm	█ 683	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---

## ADDITIVES

Calcium	ppm	█ 580	---	---	---
Magnesium	ppm	█ 8	---	---	---
Zinc	ppm	█ 87	---	---	---
Phosphorus	ppm	█ 736	---	---	---
Barium	ppm	█ 163	---	---	---
Boron	ppm	█ 295	---	---	---

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal for OEM. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VP718610

**Unique No:** 10876570

**Signed:** Doug Bogart

**Report Date:** 15 Feb 2024

# OIL ANALYSIS REPORT



## GRAPHS

