



## SUSAN EIDE DILLON VOLVO PENTA 3940028072 - PORT IPS

Sample No: VPA060408

**Oil Type:** VOLVO API GL-5 SAE 75W90

SAMPLE INFORMATION					
Sample Number		VPA060408	VPA045529		
Sample Date		20 Feb 2024	07 Mar 2023		
Machine Hours		913	0		
Oil Hours		0	0		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	NORMAL		
OIL CONDITION					
Visc @ 40°C	cSt	<b>106</b>	□105		
CONTAMINATION	N				
Water	%	NEG	NEG		
Silicon	ppm	9	12		
Sodium	ppm	<b>-&lt;1</b>	<b>2</b>		
Potassium	ppm	<b>■</b> 0	<b>3</b>		
WEAR METALS					
PQ		<b>■</b> 22	<b>2</b> 3		
Iron	ppm	<b>■</b> 54	<b>1</b> 71		
Copper	ppm	4	6		
Lead	ppm	0	0		
Tin	ppm	<1	<1		
Aluminum	ppm	<1	1		
Chromium	ppm	<b>■&lt;1</b>	<b>1</b>		
Molybdenum	ppm	<b>■</b> 0	<b>2</b>		
Nickel	ppm	<b>■&lt;1</b>	<b></b>		
Titanium	ppm	0	<1		
Silver	ppm	0	0		
Manganese	ppm	<b>1</b>	<b>5</b>		
Vanadium	ppm	0	<1		
ADDITIVES					
Calcium	ppm	<b>7</b>	<b>■</b> 31		
Magnesium	ppm	■0	102		
Zinc	ppm	<b>0</b>	<b>0</b>		
Phosphorus	ppm	<b>1245</b>	<b>1247</b>		
Barium	ppm	<b>0</b>	<b>0</b>		
Boron	ppm	<b>278</b>	■300		

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP794951

 Unique No:
 10890134

 Signed:
 Don Baldridge

 Report Date:
 24 Feb 2024

## **OIL ANALYSIS REPORT**



