



CHARLIE WICKERS 502799 CUMMINS D210918558 - GENSET

Sample No: VPA060249

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA060249	 	
Sample Date		21 Feb 2024	 	
Machine Hours		259	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
OIL CONDITION				
Visc @ 100°C	cSt	13.0	 	
Base Number (BN)	mg KOH/g	7.8	 	
Oxidation (PA)	%	68	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■0.1	 	
Nitration (PA)	%	63	 	
Sulfation (PA)	%	54	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■13	 	
Sodium	ppm	6	 	
Potassium	ppm	8	 	
WEAR METALS				
Iron	ppm	1 3	 	
Copper	ppm	7	 	
Lead	ppm	■0	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	4	 	
Chromium	ppm	■1	 	
Molybdenum	ppm	15	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	■ <1	 	
Silver	ppm	■0	 	
Manganese	ppm	1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	2724	 	
Magnesium	ppm	238	 	
Zinc	ppm	1580	 	
Phosphorus	ppm	1265	 	
Barium	ppm	2	 	
Boron	ppm	179	 	

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107

Contact: WILLOW YANARELLA service@coastalmarineengine.com

T: (206)784-3703 F: (206)784-8823

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP794951Unique No:10902232Signed:Don BaldridgeReport Date:02 Mar 2024

OIL ANALYSIS REPORT



