



## MATIC MATIC VOLVO PENTA 2004029188 - PORT DIESEL ENGINE

Sample No: VPA058286
Oil Type: {unknown}

SAMPLE INFORM	ATION			
	TITON			
Sample Number		VPA058286	 	
Sample Date		03 Mar 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	■13.16	 	
Oxidation (PA)	%	57	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	NEG ■0.1		
Nitration (PA)	%	<b>■</b> 0.1 48	 	
Sulfation (PA)	%	48 51	 	
, ,		NEG	 	
Glycol Fuel	%	<1.0		
Silicon	ppm	<b>3</b>	 	
Sodium	ppm	<b>■</b> <1	 	
Potassium	ppm	<b>■</b> 0	 	
WEAR METALS				
Iron	ppm	<b>■</b> 7	 	
Copper	ppm	<b>3</b>	 	
Lead	ppm	<b>2</b>	 	
Tin	ppm	<1	 	
Aluminum	ppm	<b>■</b> 3	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>56</b>	 	
Nickel	ppm	■1	 	
Titanium	ppm	■0	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	<b>1010</b>	 	
Magnesium	ppm	<b>■</b> 953	 	
Zinc	ppm	■ 1341	 	
Phosphorus		<b>1150</b>	 	
Barium	ppm		 	
	ppm	<b>■</b> 0		
Boron	ppm	■11	 	

## Harry's Marine Service LLC

1141 N. Citrus St.
Orange, CA
US 92887
Contact: TARAH AULD
info@harrysmarine.com
T: (714)771-7899
F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP867279Unique No:10911407Signed:Doug BogartReport Date:04 Mar 2024





