



ZF 20009765 - INBOARD - STARBOARD GEARBOX

Sample No: VPA060897 Oil Type: SAE 40W

SAMPLE INFORMA	TION			
	ITION			
Sample Number		VPA060897	 	
Sample Date		05 Mar 2024	 	
Machine Hours		1426	 	
Oil Hours		84	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	■ 85.1	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	3	 	
Sodium	ppm	2	 	
Potassium	ppm	0	 	
WEAR METALS				
PQ		■17	 	
Iron	ppm	■14	 	
Copper	ppm	■30	 	
Lead	ppm	<u>▲</u> 58	 	
Tin	ppm	0	 	
Aluminum	ppm	<u></u> 32	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	82	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm		 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	2134	 	
Magnesium	ppm	176	 	
Zinc	ppm	1020	 	
Phosphorus	ppm	952	 	
Barium	ppm	■ 0	 	
Boron	ppm	23	 	

CAROLINA MARINE DIESEL

PO BOX 24159 HILTON HEAD, SC US 29925 Contact: KEVIN JACKSON cmdieselsc@gmail.com T: (843)830-9202 F: (843)681-9976

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The aluminum level is abnormal. The copper level is abnormal. The condition of the oil is acceptable for the time in service.

Depot: CARHILSC
Unique No: 10913962
Signed: Jonathan Hester
Report Date: 11 Mar 2024





