



46437 ZF 20206610 - INBOARD - STARBOARD GEARBOX

Sample No: VPA060941
Oil Type: {unknown}

SAMPLE INFORMA	ATION			
Sample Number		VPA060941	 	
Sample Number		01 Mar 2024	 	
Machine Hours		1165	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
		HORWAL		
OIL CONDITION				
Visc @ 40°C	cSt	125	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	1123	 	
Sodium	ppm	■3	 	
Potassium	ppm	■0	 	
WEAR METALS				
PQ		17	 	
Iron	ppm	6	 	
Copper	ppm	■89	 	
Lead	ppm	■ <1	 	
Tin	ppm	■0	 	
Aluminum	ppm	■1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	18	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	2493	 	
Magnesium	ppm	69	 	
Zinc	ppm	839	 	
Phosphorus	ppm	766	 	
Barium	ppm	0	 	
Boron	ppm	4	 	

ONE WATER YACHT

3201 W STATE RD 84 FR LAUDERDALE, FL US 33312 Contact: ANTHONY VIGLIOTTI avigliotti@owyg.com

avigliotti@owyg.com T: (954)292-4857

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP1134827Unique No:10915210Signed:Don BaldridgeReport Date:10 Mar 2024

OIL ANALYSIS REPORT



