



GALEON - ARTURO HERRERA VOLVO PENTA A877539 - PORT DIESEL ENGINE

Sample No: VPA060840

Oil Type: **DIESEL ENGINE OIL SAE 15W40**

SAMPLE INFORMAT	TION			
Sample Number		VPA060840	 	
Sample Date		06 Mar 2024	 	
Machine Hours		516	 	
Oil Hours		94	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
OIL CONDITION				
Visc @ 100°C	cSt	13.6	 	
Base Number (BN)	mg KOH/g	■9.5	 	
Oxidation (PA)	%	57	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■0.3	 	
Nitration (PA)	%	49	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■5	 	
Sodium	ppm	1	 	
Potassium	ppm	4	 	
WEAR METALS				
Iron	nnm	1 6	 	
Copper	ppm	6	 	
Lead	ppm ppm	■ <1	 	
Tin	ррт	■<1 ■<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	□ <1	 	
Molybdenum	ppm	46	 	
Nickel	ppm	1	 	
Titanium	ppm	 <1	 	
Silver	ppm	- <1	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
	10.10.100	m1254		
Calcium Magnesium	ppm	■ 1351 ■ 767	 	
_	ppm	■ 767		
Zinc	ppm		 	
Phosphorus Barium	ppm	■1128		
	ppm	□ 0	 	
Boron	ppm	46	 	

FLORIDA DETROIT DIESEL - 531006 - 1125774

1128 CHESTNUT AVE PANAMA CITY, FL US 32401 Contact: RICHARD ROBERTS

ri.roberts@kirbycorp.com T: (850)763-7656

F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: **VPFLOPAN** Unique No: 10922803 Signed: Don Baldridge Report Date: 12 Mar 2024

OIL ANALYSIS REPORT



