



NORTHERN LIGHTS 7732-51397 - CENTER GENSET

Sample No: VPA059482

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA059482	 	
Sample Date		13 Mar 2024	 	
Machine Hours		0	 	
Oil Hours		100		
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	■13.7	 	
Base Number (BN)	mg KOH/g	■ 9.2	 	
Oxidation (PA)	%	65	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	■0.1	 	
Nitration (PA)	%	61	 	
Sulfation (PA)	%	53	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■7	 	
Sodium	ppm	<u></u> 5	 	
Potassium	ppm	■3	 	
	le le			
WEAR METALS				
Iron	ppm	21	 	
Copper	ppm	■5	 	
Lead	ppm	■<1	 	
Tin	ppm	■<1	 	
Aluminum	ppm	10	 	
Chromium	ppm	■2	 	
Molybdenum	ppm	■ 50	 	
Nickel	ppm	O	 	
Titanium	ppm	1	 	
Silver	ppm	■ <1	 	
Manganese	ppm	■ <1	 	
Vanadium	ppm	<1	 	
ADDITIODA				
Calcium	nnm	□ 1533	 	
Magnesium	ppm	■ 1533 ■ 554	 	
Zinc				
	ppm	■ 1127 ■ 959	 	
Phosphorus	ppm	■ 858	 	
Barium	ppm	2	 	
Boron	ppm	38	 	

SMART DIESEL SERVICE

102 NW 133RD AVE, UNIT 103 PLANTATION, FL US 33325 Contact: ANDRES GARMENDIA smartdieselservice@gmail.com T: (954)258-8100 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VPSMAPLAUnique No:10939499Signed:Jonathan HesterReport Date:22 Mar 2024

OIL ANALYSIS REPORT



