



MARITIMO 50 CUMMINS H140733381 - GENSET

Sample No: VPA059932

Oil Type: DIESEL ENGINE OIL SAE 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA059932	 	
Sample Date		21 Mar 2024	 	
Machine Hours		1234	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
Sumple Status		HORWAL		
OIL CONDITION				
Visc @ 100°C	cSt	12.9	 	
Base Number (BN)	mg KOH/g	■9.9	 	
Oxidation (PA)	%	55	 	
CONTAMINATION				
Water	%	NEG	 	
Soot %	%	NEG ■ 0.1	 	
Nitration (PA)	%	40	 	
Sulfation (PA)	%	50	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■3	 	
Sodium	ppm		 	
Potassium	ppm	0	 	
WEADMETALS		_		
WEAR METALS				
Iron	ppm	■ 3	 	
Copper	ppm	2	 	
Lead	ppm	■0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■ 0	 	
Molybdenum	ppm	■ 58	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	■0	 	
Silver	ppm	■0	 	
Manganese	ppm	■0	 	
Vanadium	ppm	<1	 	
ADDITIDDA				
Calcium	ppm	1126	 	
Magnesium	ppm	974	 	
Zinc	ppm	1240	 	
Phosphorus	ppm	1074	 	
Barium	ppm	■ 0	 	
Boron	ppm	4	 	

Marine International Diesels Inc.

3600 HACIENDA BLVD UNIT G DAVIE, FL US 33314 Contact: ASHANTI BURKE aburke@midiflorida.com T: (954)761-1086 F: (954)761-1186

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VP694356Unique No:10943347Signed:Don BaldridgeReport Date:28 Mar 2024

OIL ANALYSIS REPORT



