OIL ANALYSIS REPORT

STRZYNSKI 510 SEA RAY - PORT GEARBOX

Sample No:	VPA06129654
Oil Type:	{unknown}

SAMPLE INFORMATION

Sample Number		VPA06129654	 	
Sample Date		25 Mar 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	156	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm		 	
Sodium	ppm		 	
Potassium	ppm	■ <1	 	
WEAR METALS	1.1.			
PQ		∎16	 	
Iron	ppm	148	 	
Copper	ppm	∎14	 	
Lead	ppm	□1	 	
Tin	ppm		 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	45	 	
Nickel	ppm	2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	13	 	
Magnesium	ppm	<1	 	
Zinc	ppm	3	 	
Phosphorus	ppm	233	 	
Barium	ppm	0	 	
Boron	ppm	<1	 	

VOLVO PENTA

Michigan Yachtcrafters Inc 31785 S. River Road HARRISON TOWNSHIP, MI US 48045 Contact: Garrett Cassidy michiganyachtservice@gmail.com T:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VP151756

 Unique No:
 10943805

 Signed:
 Jonathan Hester


 Report Date:
 02 Apr 2024

Contact/Location: Garrett Cassidy - VP151756

OIL ANALYSIS REPORT



GRAPHS



Report Id: VP151756 [WUSCAR] 06129654 (Generated: 04/02/2024 12:12:42) Rev: 2

Contact/Location: Garrett Cassidy - VP151756