



WINDSERVE JOURNEY MAB549506 VOLVO PENTA 10132222706 - PORT IPS

Sample No: VPA048431

Oil Type: VOLVO PENTA GL-5 SAE 75W90

SAMPLE INFORM	IATION				
Sample Number		VPA048431			
Sample Date		21 Mar 2024			
Machine Hours		350			
Oil Hours		315			
Oil Changed		Not Changd			
Sample Status		NORMAL			
	_	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_	_	
OIL CONDITION					
Visc @ 40°C	cSt	■ 99.1			
CONTAMINATION	N				
Water	%	NEG			
Silicon	ppm	5			
Sodium	ppm	■ 5			
Potassium	ppm	■ 5			
WEAR METALS					
PQ		27			
Iron	ppm	64			
Copper	ppm	3			
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	<1			
Chromium	ppm	■ 0			
Molybdenum	ppm	0			
Nickel	ppm	0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	5			
Vanadium	ppm	0			
ADDITIVES					
Calcium	ppm	■ 33			
Magnesium	ppm	840			
Zinc	ppm	10			
Phosphorus	ppm	1559			
Barium	ppm	■0			
Boron	ppm	■ 537			
	1-1				

STEWART AND STEVENSON (ADDA)

PO BOX 950 LODI, NJ US 07644 Contact: DAVID TAGLIERI d.taglieri@kirbycorp.com T: (508)263-5502 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP166699Unique No:10950544Signed:Don BaldridgeReport Date:01 Apr 2024





